



Product History – AV5103

CHANGE OR OCCURRENCE	DATE	SER-NO	Please note – Non DTS units (units <s/n:3000 that have not been upgraded to DTS spec) requiring software upgrade should use revision R4B12 and <u>not</u> a later revision.
AV5103 introduced	Jun 1996		
AV5103 upgraded : <ul style="list-style-type: none">❖ Main Processor IC (Zoran IC) Upgraded from A2 to A3 spec – allows the Limbik software upgrade to function correctly.❖ DSP (digital signal processing) section of the circuitry incorporated onto a 'piggy-back' board instead of the main board allowing easier future upgrade.	Apr 1997	1400 approx	
Limbik Software Installed as standard Upgrade Available – contact Linn order processing	Sep 1998	1672	
Silver AV5103 introduced in addition to the standard Black finish	Dec 1999	N/A	
DTS decoding capability included as standard Upgrade available – see Linfo Website (linfo.linn.co.uk – Product Information) or contact Linn Order Processing for details.	Jan 2000	3000	
Software Upgraded to R5B14 and Display Upgraded. <ul style="list-style-type: none">❖ Software Upgrade (to revision R5B14) allows AV5103 to support the INLINE video switcher, which adds up to 6 additional video sources and allows new VFD display to function. See www.inlineinc.com for details of Inline switcher.❖ Display upgraded from LCD (Liquid Crystal Display) to VFD type (Vacuum Fluorescent Display) which is much brighter, is coloured blue and is more aesthetically pleasing.	Jun 2000	3276	
Software Upgraded to R5B17 Main changes: <ul style="list-style-type: none">❖ Inline Video Switcher can now be controlled via RS232❖ Improved controllability of Inline Video Switcher	Mar 2001	622550	
DSP (Digital Signal Processing) Board changed to eradicate any chance of occurrence of an intermittent fault, found on a small percentage of units between serial number 3000 & 622550. The fault caused multi-channel digital signal to sometimes cut off. Upgrade available – see Linfo Website (http://linfo.linn.co.uk – Product Information – AV5103 DSP Repair Procedure	Mar 2001	622550	
Software Upgraded to R5B18 Main change: <ul style="list-style-type: none">❖ Enhancement of subwoofer performance in DTS mode	June 2001	633950	

Disclaimer. Linn product histories are provided as a rough guide only – i.e. a basic overview of some of the more significant changes to a product's design and not a comprehensive list. Linn Products Ltd does not therefore guarantee that this list is accurate or up to date and accepts no responsibility for any problems arising as a result of its use.



Copyright © Linn Products Limited. All rights reserved.